Annexure D

	BU	ILDING SAFE	EIYCERTIFIC	ATE				
No.			Dated: 13					
It is certified that the building or premises) at				- · · · · · · · · · · · · · · · · · · ·	00.L. (nam	ne of the		
	iddress) is ha			r details below:	***************************************			
Detail of Block(s) in	Block	Block	Block	Block	Block	Block		

Detail of Block(s) in	Block	Block	Block	Block	Block	Block
school	(1)	(2)	(3)	(4)	(5)	(6)
No. of Floor(s) in the Block	(G)	2				

The building is owned/occupied by CRIMSON WORLD SCHOOL of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of साभी हो. अभिन्न हो निमा (Name of Department/ Govt.) on 22/07/2024 (date of inspection) in the Ms. RITU TAMBON, GANPTI, TDI CITY (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for with rule and subject to compliance of the specific conditions as appended.

Issued on ... 13 07 2024 at ... AGRA by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal:

Name:

Designation

Name & Address of Department/ Office:

66 | Page